

Cell Phone Interfacing Application Guide

Revised 12-19-07

Make	Model	Year	Installation Notes	Harness	MSS Required
Acura	CL	2000-2003	Not compatible with Subwoofers or premium amplified systems (more than 6 speakers). For 20 pin radio connectors.	PPH1721	YES
	CL	1996-1999	For 16 pin radio connectors.	PPH1720	YES
	Integra	1999-2001	Not compatible with Subwoofers or premium amplified systems (more than 6 speakers). For 20 pin radio connectors.	PPH1721	YES
	Integra	1986-1998	For 16 pin radio connectors.	PPH1720	YES
	Legend	1986-1996	For 16 pin radio connectors.	PPH1720	YES
	MDX	2001-2005	Not compatible with Subwoofers or premium amplified systems (more than 6 speakers). For 20 pin radio connectors.	PPH1721	YES
	NSX	1991-2004	For 16 pin radio connectors.	PPH1720	YES
	RL	1999-2005	Not compatible with Subwoofers or premium amplified systems (more than 6 speakers). For 20 pin radio connectors.	PPH1721	YES
	RL	1996-1998	For 16 pin radio connectors.	PPH1720	YES
	RSX	2002-2005	Not compatible with Subwoofers or premium amplified systems (more than 6 speakers). For 20 pin radio connectors.	PPH1721	YES
	RSX (Type S)	2002-2005	Not compatible with Subwoofers or premium amplified systems (more than 6 speakers). For 20 pin radio connectors.	PPH1721	YES
	SLX	1996-1999	For 16 pin radio connectors.	PPH7712	YES
	TL	1999-2003	Not compatible with Subwoofers or premium amplified systems (more than 6 speakers). For 20 pin radio connectors.	PPH1721	YES
	TL	1996-1998	For 16 pin radio connectors.	PPH1720	YES
	TSX	2004-2005	Not compatible with Subwoofers or premium amplified systems (more than 6 speakers). For 20 pin radio connectors.	PPH1721	YES
	Vigor	1992-1994	For 16 pin radio connectors.	PPH1720	YES
Audi	A4	2000-2003	For 16 pin radio connectors.	PPH1784	YES
	A4 Sedan	1995-2002	For 16 pin radio connectors.	PPH1784	YES
	A6	2000-2003	For 16 pin radio connectors.	PPH1784	YES
	A8	1995-2005	For 16 pin radio connectors.	PPH1784	YES
	All Models (96-99)	1996-1999	For 16 pin radio connectors.	PPH1784	YES
	Avant S4 RS4	1995-2002	For 16 pin radio connectors.	PPH1784	YES
	Cabriolet	1989-2005	For 16 pin radio connectors.	PPH1784	YES
	Coupe	1989-2005	For 16 pin radio connectors.	PPH1784	YES
	Quattro	1989-2005	For 16 pin radio connectors.	PPH1784	YES
	Quattro (Ur)	1982-1986	For 16 pin radio connectors.	PPH1784	YES
	S4	2000-2003	For 16 pin radio connectors.	PPH1784	YES
	S6	1995-2002	For 16 pin radio connectors.	PPH1784	YES
	S6	1994-2003	For 16 pin radio connectors.	PPH1784	YES
	S8	1995-2005	For 16 pin radio connectors.	PPH1784	YES
TT	1999-2005	For 16 pin radio connectors.	PPH1784	YES	
BMW	3 Series	1992-2001	For 17 pin radio connectors.	PPH8590	YES
	3 Series	2002-2005	For 16 pin radio connectors.	PPH9003	YES
	Mini Cooper	2002-2005	For 16 pin radio connectors.	PPH9003	YES
	X5	2000-2006	For 16 pin radio connectors.	PPH9003	YES
	Z3	1996-2002	For 17 pin radio connectors.	PPH8590	YES
	Z4	2000-2006	For 17 pin radio connectors.	PPH8590	YES
	Z8	2000-2004	For 17 pin radio connectors.	PPH8590	YES
Buick	Century	1997-2005	Not compatible with Monsoon or other external amplifiers.. For 32 pin radio connectors.	PPH2001	YES
	Century	1988-1996	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Electra	1988-1990	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	LaSabre	1995-1999	Not compatible with Monsoon or other external amplifiers.. For 32 pin radio connectors.	PPH2001	YES
	LaSabre	1988-1994	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Park Avenue	1995-2005	Not compatible with Monsoon or other external amplifiers.. For 32 pin radio connectors.	PPH2001	YES
	Park Avenue	1988-1994	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Rainier	2004-2007	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF 1000 (sold separately)	GMCSS2	NO
	Regal	1995-2004	Not compatible with Monsoon or other external amplifiers.. For 32 pin radio connectors.	PPH2001	YES
	Regal	1988-1994	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Rendezvous	2002-2007	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF 1000 (sold separately)	GMCSS2	NO
	Riviera	1996-1999	Not compatible with Monsoon or other external amplifiers.. For 32 pin radio connectors.	PPH2001	YES
	Riviera	1992-1995	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Roadmaster	1995-1996	Not compatible with Monsoon or other external amplifiers.. For 32 pin radio connectors.	PPH2001	YES
	Roadmaster	1991-1994	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Skylark	1996-1998	Not compatible with Monsoon or other external amplifiers.. For 32 pin radio connectors.	PPH2001	YES
	Skylark	1989-1995	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES

Cadillac	Catera	1997-2001	Not compatible with Bose or other amplified systems. For 32 pin radio connectors.	PPH2001	YES
	Coupe De Ville	1988-1991	Not compatible with Bose or other amplified systems. For 21 pin radio connectors.	PPH1858	YES
	DeVille	1996-1999	Not compatible with Bose or other amplified systems. For 32 pin radio connectors.	PPH2001	YES
	DeVille	1988-1995	Not compatible with Bose or other amplified systems. For 21 pin radio connectors.	PPH1858	YES
	Escalade	2007	Vehicle must have OnStar Installed. Requires MOT1000 Harness (sold separately)	GMCSS3	NO
	Escalade	2003-2006	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness (sold separately)	GMCSS2	NO
	Escalade	1999-2002	Not compatible with Bose or other amplified systems. For 21 pin radio connectors.	PPH1858	YES
	Fleetwood	1994-1996	Not compatible with Bose or other amplified systems. For 32 pin radio connectors.	PPH2001	YES
	Fleetwood	1988-1993	Not compatible with Bose or other amplified systems. For 21 pin radio connectors.	PPH1858	YES
	Seville	1992-2005	Not compatible with Bose or other amplified systems. For 32 pin radio connectors.	PPH2001	YES
	Seville	1988-1991	Not compatible with Bose or other amplified systems. For 21 pin radio connectors.	PPH1858	YES
Chevrolet	Astro	1991-2003	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Avalanche	2007	Vehicle must have OnStar Installed. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS3	NO
	Avalanche	2003-2006	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS2	NO
	Avalanche	2002	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Beretta	1991-1996	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Berretta	1988-1990	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Blazer	1992-1994	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Camaro	1990-2003	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Caprice	1994-1996	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Caprice Classic	1991-1993	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Cavalier	2000-2005	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS2	NO
	Cavalier	1988-1999	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Celebrity	1990	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	C-K	2003-2004	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS2	NO
	Colorado	2004-2006	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS2	NO
	Corsica	1988-1996	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Corvette	1990-2004	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Express	2003-2006	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS2	NO
	Express	2001-2002	Not compatible with RDS radio or amplified systems.. For 24 pin radio connectors.	PPH2003	YES
	Express	1996-2000	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Impala	2006-2007	Vehicle must have OnStar Installed. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS3	NO
	Impala	2000-2005	Vehicle must have OnStar Installed. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS3	NO
	Impala	2000-2005	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS2	NO
	Impala SS	1994-1996	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Lumina	1990-2001	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Lumina APV	1990-1996	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Malibu	2001-2003	Vehicle must have OnStar Installed. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS3	NO
	Malibu	2001-2003	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS2	NO
	Malibu	1997-2000	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Metro	2000-2001	Not compatible with RDS radio or amplified systems.. For 24 pin radio connectors.	PPH2003	YES
	Monte Carlo	2006-2007	Vehicle must have OnStar Installed. Requires MOT1000 Harness (sold separately)	GMCSS3	NO
	Monte Carlo	2000-2005	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS2	NO
	Monte Carlo	1995-1999	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Pick up (C/K)	1988-2000	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Prism	2000-2002	Not compatible with RDS radio or amplified systems.. For 24 pin radio connectors.	PPH2003	YES
	S-10	2003-2006	For 24 pin radio connectors with out Onstar	PPH2003	YES
	S-10	2003-2006	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS2	NO
S-10	1990-2002	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES	
S-10 Extreme	2000-2003	Not compatible with RDS radio or amplified systems.. For 24 pin radio connectors.	PPH2003	YES	
Silverado	2003-2006	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS2	NO	
Silverado	1999-2002	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES	
Suburban	2007	Vehicle must have OnStar Installed. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS3	NO	
Suburban	2003-2006	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness (sold separately)	GMCSS2	NO	
Suburban	1989-2002	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES	
Tahoe	2007	Vehicle must have OnStar Installed. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS3	NO	

	Tahoe	2003-2006	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS2	NO
	Tahoe	1995-2002	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Tracker	2000-2004	Not compatible with RDS radio or amplified systems.. For 24 pin radio connectors.	PPH2003	YES
	Trailblazer	2002-2007	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS2	NO
	Van	1988-1995	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Venture	2000-2005	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS2	NO
	Venture	1997-1999	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
Chrysler					
	300	2003-2006	For 22 pin radio connectors. Not compatible with Infinity premium amplifiers.	PPH1818	YES
	300M	2002-2004	For 22 pin radio connectors.	PPH1818	YES
	300M	1999-2001	For 17 pin radio connectors.	PPH1817	YES
	Cirrus	1995-2000	For 17 pin radio connectors.	PPH1817	YES
	Concorde	2002-2004	For 22 pin radio connectors. Not compatible with Infinity premium amplifiers.	PPH1818	YES
	Concorde	1993-2001	For 17 pin radio connectors.	PPH1817	YES
	Fifth Avenue	1979-1993	For 17 pin radio connectors.	PPH1817	YES
	Laser	1984-1986	For 17 pin radio connectors.	PPH1817	YES
	Le Baron	1984-1995	For 17 pin radio connectors.	PPH1817	YES
	LHS	2002-2006	For 22 pin radio connectors. Not compatible with Infinity premium amplifiers.	PPH1818	YES
	LHS	1994-2001	For 17 pin radio connectors.	PPH1817	YES
	New Yorker	1979-1997	For 17 pin radio connectors.	PPH1817	YES
	Pacifica	2003-2006	For 22 pin radio connectors. Not compatible with Infinity premium amplifiers.	PPH1818	YES
	Prowler	2001-2002	For 17 pin radio connectors.	PPH1817	YES
	PT Cruiser	2002-2006	For 22 pin radio connectors.	PPH1818	YES
	PT Cruiser	2000-2001	For 17 pin radio connectors.	PPH1817	YES
	Sebring	2002-2005	For 22 pin radio connectors. Not compatible with Infinity premium amplifiers.	PPH1818	YES
	Sebring	1995-2001	For 17 pin radio connectors.	PPH1817	YES
	Town & Country	2002-2006	For 22 pin radio connectors. Not compatible with Infinity premium amplifiers.	PPH1818	YES
	Town & Country	1984-2001	For 17 pin radio connectors.	PPH1817	YES
	Voyager	2002-2003	For 22 pin radio connectors.	PPH1818	YES
Dodge					
	Aries	1984-1989	For 17 pin radio connectors.	PPH1817	YES
	Avenger	1995-2000	For 17 pin radio connectors.	PPH1817	YES
	Caravan	2002-2006	For 22 pin radio connectors. Not compatible with Infinity premium amplifiers.	PPH1818	YES
	Caravan	1984-2001	For 17 pin radio connectors.	PPH1817	YES
	Dakota	2002-2006	For 22 pin radio connectors. Not compatible with Infinity premium amplifiers.	PPH1818	YES
	Dakota	1987-2001	For 17 pin radio connectors.	PPH1817	YES
	Daytona	1984-1993	For 17 pin radio connectors.	PPH1817	YES
	Diplomat	1984-1989	For 17 pin radio connectors.	PPH1817	YES
	Durango	2002-2004	For 22 pin radio connectors. Not compatible with Infinity premium amplifiers.	PPH1818	YES
	Durango	1998-2001	For 17 pin radio connectors.	PPH1817	YES
	Dynasty	1988-1993	For 17 pin radio connectors.	PPH1817	YES
	Grand Caravan	2006	For 22 pin radio connectors. Not compatible with Infinity premium amplifiers.	PPH1818	YES
	Intrepid	2002-2005	For 22 pin radio connectors. Not compatible with Infinite or other amplified systems	PPH1818	YES
	Intrepid	1993-2001	For 17 pin radio connectors.	PPH1817	YES
	Lancer	1985-1989	For 17 pin radio connectors.	PPH1817	YES
	Neon	2002-2006	For 22 pin radio connectors.	PPH1818	YES
	Neon	1995-2001	For 17 pin radio connectors.	PPH1817	YES
	Omni	1984-1990	For 17 pin radio connectors.	PPH1817	YES
	Ram Pickup	2002-2006	For 22 pin radio connectors. Not compatible with Infinity premium amplifiers.	PPH1818	YES
	Ram Pickup	1984-2001	For 17 pin radio connectors.	PPH1817	YES
	Ram Van (Fullsize)	2002-2003	For 22 pin radio connectors. Not compatible with Inifinit or other amplified systems	PPH1818	YES
	Shadow	1987-1994	For 17 pin radio connectors.	PPH1817	YES
	Spirit	1989-1995	For 17 pin radio connectors.	PPH1817	YES
	Sprinter	2004-2005	For 16 pin radio connectors.	PPH1784	YES
	Stratus	2002-2005	For 22 pin radio connectors. Not compatible with Infinity premium amplifiers.	PPH1818	YES
	Stratus	1995-2001	For 17 pin radio connectors.	PPH1817	YES
	Van (Fullsize)	1978-2001	For 17 pin radio connectors.	PPH1817	YES
	Viper	2003-2006	For 22 pin radio connectors. Not compatible with Infinity premium amplifiers.	PPH1818	YES
Eagle					
	Talon	1995-1998	For 14 pin radio connectors.	PPH7001	YES
Ford					
	Aerostar	1985-1997	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
	Aspire	1994-1997	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
	Bronco (Full Size)	1987-1996	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
	Bronco II	1986-1990	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES

Contour	1995-2000	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
Crown Victoria	2003-2007	Not compatible with Premium Amplified Systems. For 24 pin radio connectors.	PPH5800	YES
Crown Victoria	2003-2007	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors.	PXFDHF2	NO
Crown Victoria	2003-2007	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS2	NO
Crown Victoria	1998-2002	Make sure radio has No phone symbol on radio buttons.. Not compatible with premium amplified systems.. For 16 pin radio connectors.	PPH1771	YES
Crown Victoria	1998-2002	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio.	PXFDHF	NO
Crown Victoria	1998-2002	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS1	NO
Crown Victoria	1986-1994	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
Econoline	1998-2003	Make sure radio has No phone symbol on radio buttons.. Not compatible with premium amplified systems nor Navigation.. For 16 pin radio connectors.	PPH1771	YES
Econoline	1998-2003	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio.	PXFDHF	NO
Econoline	1998-2003	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS1	NO
Econoline	1987-1997	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
Econoline E150-E350	2004-2006	Not compatible with Premium Amplified Systems. For 24 pin radio connectors.	PPH5800	YES
Escape	2004-2007	Not compatible with Premium Amplified Systems. For 24 pin radio connectors.	PPH5800	YES
Escape	2004-2007	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors.	PXFDHF2	NO
Escape	2004-2007	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors. Requires MOT1000 harness when using with IHF 1000 (sold separately)	FCSS2	NO
Escape	2001-2003	Make sure radio has No phone symbol on radio buttons.. Not compatible with premium amplified systems.. For 16 pin radio connectors.	PPH1771	YES
Escape	2001-2003	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio.	PXFDHF	NO
Escape	2001-2003	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS1	NO
Escort	1986-1996	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
Excursion	2000-2005	Not compatible with Premium Amplified Systems. For 24 pin radio connectors.	PPH5800	YES
Excursion	2000-2005	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio.	PXFDHF	NO
Excursion	2000-2005	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS1	NO
Excursion	2000-2004	Make sure radio has No phone symbol on radio buttons.. Not compatible with premium amplified nor Navigation systems. For 16 pin radio connectors.	PPH1771	YES
Excursion	2005	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors.	PXFDHF2	NO
Excursion	2005	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS2	NO
Expedition	2003-2006	Not compatible with Premium Amplified Systems. For 24 pin radio connectors.	PPH5800	YES
Expedition	2003-2006	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors.	PXFDHF2	NO
Expedition	2003-2006	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors. Requires MOT1000 harness when using with IHF 1000 (sold separately)	FCSS2	NO
Expedition	1998-2002	Make sure radio has No phone symbol on radio buttons.. Not compatible with premium amplified nor Navigation systems. For 16 pin radio connectors.	PPH1771	YES
Expedition	1998-2002	Make sure radio has Phone button on radio face.. Not compatible with Navigation radio. For 20 pin radio connectors.	PXFDHF	NO
Expedition	1998-2002	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS1	NO
Explorer	2004-2008	Not compatible with Premium Amplified Systems. For 24 pin radio connectors.	PPH5800	YES
Explorer	2004-2008	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors.	PXFDHF2	NO
Explorer	2004-2008	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS2	NO
Explorer	1998-2004	Make sure radio has No phone symbol on radio buttons.. Not compatible with premium amplified systems.. For 16 pin radio connectors.	PPH1771	YES
Explorer	1998-2004	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio.	PXFDHF	NO
Explorer	1998-2004	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS1	NO
Explorer	1991-1997	Not compatible with premium amplified systems. For 8+8 pin radio connectors.	PPH1770	YES
Explorer Sport Trac	2004-2008	Not compatible with Premium Amplified Systems. For 24 pin radio connectors.	PPH5800	YES
Explorer Sport Trac	2007-2008	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors.	PXFDHF2	NO
Explorer Sport Trac	2007-2008	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors. Requires MOT1000 harness when using with IHF 1000 (sold separately)	FCSS2	NO
Explorer Sport Trac	2000-2005	Make sure radio has No phone symbol on radio buttons.. Not compatible with premium amplified systems.. For 16 pin radio connectors.	PPH1771	YES
Explorer Sport Trac	2000-2005	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio.	PXFDHF	NO
Explorer Sport Trac	2000-2005	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS1	NO
F Series Pickup	2005-2008	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors.	PXFDHF2	NO

F Series Pickup	2005-2008	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS2	NO
F Series Pickup	2004-2005	Not compatible with Premium Amplified Systems. For 24 pin radio connectors.	PPH5800	YES
F Series Pickup	1999-2004	Make sure radio has No phone symbol on radio buttons.. Not compatible with premium amplified systems.. For 16 pin radio connectors.	PPH1771	YES
F Series Pickup	1999-2004	Make sure radio has Phone button on radio face. For 20 pin radio connectors.	PXFDHF	NO
F Series Pickup	1999-2004	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS1	NO
F Series Pickup	1986-1998	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
F-150 Heritage	2004-2005	Make sure radio has No phone symbol on radio buttons.. Not compatible with premium amplified systems.. For 16 pin radio connectors.	PPH1771	YES
Five Hundred	2005-2007	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors.	PXFDHF2	NO
Five Hundred	2005-2007	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS2	NO
Five Hundred	2006-2007	Not compatible with Premium Amplified Systems. For 24 pin radio connectors.	PPH5800	YES
Focus	2005-2007	Not compatible with Premium Amplified Systems. For 24 pin radio connectors.	PPH5800	YES
Focus	2005-2007	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors.	PXFDHF2	NO
Focus	2005-2007	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS2	NO
Focus	2000-2004	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
Freestar	2004-2007	Not compatible with Premium Amplified Systems. For 24 pin radio connectors.	PPH5800	YES
Freestar	2004-2007	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors.	PXFDHF2	NO
Freestar	2004-2007	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS2	NO
Freestyle	2005-2007	Not compatible with Premium Amplified Systems. For 24 pin radio connectors.	PPH5800	YES
Freestyle	2005-2007	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors.	PXFDHF2	NO
Freestyle	2005-2007	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS2	NO
Fusion	2006-2008	Not compatible with Premium Amplified Systems. For 24 pin radio connectors.	PPH5800	YES
Fusion	2006-2008	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors.	PXFDHF2	NO
Fusion	2006-2008	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS2	NO
LTD	1986-1991	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
Mustang	2005-2007	Not compatible with Premium Amplified Systems. For 24 pin radio connectors.	PPH5800	YES
Mustang	2005-2007	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors.	PXFDHF2	NO
Mustang	2005-2007	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS2	NO
Mustang	2001-2004	Make sure radio has No phone symbol on radio buttons.. Not compatible with premium amplified systems.. For 16 pin radio connectors.	PPH1771	YES
Mustang	2001-2004	Make sure radio has Phone button on radio face. For 20 pin radio connectors.	PXFDHF	NO
Mustang	2001-2004	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS1	NO
Mustang	1986-2000	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
Probe	1989-1997	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
Ranger	1998-2005	Make sure radio has No phone symbol on radio buttons.. Not compatible with premium amplified systems.. For 16 pin radio connectors.	PPH1771	YES
Ranger	1998-2005	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio.	PXFDHF	NO
Ranger	1998-2005	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS1	NO
Ranger	1986-1997	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
Taurus	1986-1995	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
Tempo	1986-1994	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
Thunderbird	2004-2005	Not compatible with Premium Amplified Systems. For 24 pin radio connectors.	PPH5800	YES
Thunderbird	2004-2005	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors.	PXFDHF2	NO
Thunderbird	2004-2005	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS2	NO
Thunderbird	2002-2005	Make sure radio has No phone symbol on radio buttons.. Not compatible with premium amplified systems.. For 16 pin radio connectors.	PPH1771	YES
Thunderbird	2002-2005	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio.	PXFDHF	NO
Thunderbird	2002-2005	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS1	NO
Thunderbird	1986-1997	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
Windstar	1999-2003	Make sure radio has No phone symbol on radio buttons.. Not compatible with premium amplified systems.. For 16 pin radio connectors.	PPH1771	YES
Windstar	1999-2003	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio.	PXFDHF	NO
Windstar	1999-2003	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS1	NO
Windstar	1995-1998	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES

Geo	Metro	2000-2001	Not compatible with RDS radio or amplified systems.. For 24 pin radio connectors.	PPH2003	YES
	Prism	2000-2002	Not compatible with RDS radio or amplified systems.. For 24 pin radio connectors.	PPH2003	YES
	Prism	1989-1992	Not compatible with Premium Amplified or other external amplifiers.. For 10+6 pin radio connectors.	PPH1761	YES
GMC					
GMC	Canyon	2004-2006	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS2	NO
	Envoy	2002-2007	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS2	NO
	Envoy	1998-2001	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	G-Series	1988-1995	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Jimmy	1990-2001	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Pick Up (C/K)	1988-2000	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	S-15	1992-1993	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Safari	1992-2005	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Savana	2003-2007	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS2	NO
	Savana	001-2007+C45	Not compatible with RDS Radio (CD/Cassette deck or 6-disc changer). For 24 pin radio connectors.	PPH2003	YES
	Savana	1996-2000	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Sierra	2003-2006	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS2	NO
	Sierra	1999-2002	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Sonoma	2002-2004	Not compatible with RDS radio or amplified systems.. For 24 pin radio connectors.	PPH2003	YES
	Sonoma	1994-2002	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Suburban	1988-1999	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Yukon	2007	Vehicle must have OnStar Installed. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS3	NO
Yukon	2003-2006	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS2	NO	
Yukon	1992-2002	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES	
Honda					
Honda	Accord	1998-2007	Not Compatible with Factory Amplified Systems. For 20 pin radio connectors.	PPH1721	YES
	Accord	1986-1997	For 16 pin radio connectors.	PPH1720	YES
	Accord LS/ES/aut	2001-2007	Not Compatible with Factory Amplified Systems. For 20 pin radio connectors.	PPH1721	YES
	Civic	1999-2000	For 16 pin radio connectors.	PPH1720	YES
	Civic	1999-2005	For 20 pin radio connectors.	PPH1721	YES
	Civic	1986-1995	For 16 pin radio connectors.	PPH1720	YES
	Civic EX	1996-1998	For 16 pin radio connectors.	PPH1720	YES
	Civic Hybrid	2001-2005	For 20 pin radio connectors.	PPH1721	YES
	Civic Si	2002-2005	For 20 pin radio connectors.	PPH1721	YES
	CRV	1999-2006	For 20 pin radio connectors.	PPH1721	YES
	CRV	1997-1998	For 16 pin radio connectors.	PPH1720	YES
	CRX	1986-1991	For 16 pin radio connectors.	PPH1720	YES
	Del Sol	1993-1997	For 16 pin radio connectors.	PPH1720	YES
	Element	2002-2007	Not Compatible with Factory Amplified Systems. For 20 pin radio connectors.	PPH1721	YES
	HR-V	1999-2005	For 20 pin radio connectors.	PPH1721	YES
	Insight	2001-2006	For 20 pin radio connectors.	PPH1721	YES
	Integra	1998-2005	For 20 pin radio connectors.	PPH1721	YES
	Jazz	2002-2005	For 20 pin radio connectors.	PPH1721	YES
	Legend	1996-2000	For 20 pin radio connectors.	PPH1721	YES
	Logo	1999-2005	For 20 pin radio connectors.	PPH1721	YES
	Odyssey	1999-2007	Not Compatible with Factory Amplified Systems. For 20 pin radio connectors.	PPH1721	YES
	Odyssey	1995-1998	For 16 pin radio connectors.	PPH1720	YES
	Passport	1996-1997	For 16 pin radio connectors.	PPH7712	YES
	Pilot	2003-2006	Not Compatible with Factory Amplified Systems. For 20 pin radio connectors.	PPH1721	YES
	Prelude	1999-2005	Not Compatible with Factory Amplified Systems. For 20 pin radio connectors.	PPH1721	YES
	Prelude	1986-1998	For 16 pin radio connectors.	PPH1720	YES
	Ridgeline	2006-2007	Not Compatible with Factory Amplified Systems. For 20 pin radio connectors.	PPH1721	YES
	S2000	2000-2006	Not Compatible with Factory Amplified Systems. For 20 pin radio connectors.	PPH1721	YES
	Shuttle	1996-2005	For 20 pin radio connectors.	PPH1721	YES
	Shuttle ES aut.	2001-2005	For 20 pin radio connectors.	PPH1721	YES
Shuttle ES aut. Van.	2001-2005	For 20 pin radio connectors.	PPH1721	YES	
Stream	2001-2005	For 20 pin radio connectors.	PPH1721	YES	
Hummer					
Hummer	H2	2002-2007	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS2	NO
	H3	2005-2007	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS2	NO
Infiniti					
Infiniti	G20	1999-2002	Not compatible with Premium Amplified Systems. For 12+6 pin radio connectors.	PPH7550	YES
	I 30	1996-1999	Not compatible with Premium Amplified Systems. For 12+6 pin radio connectors.	PPH7550	YES

	I 30 / I 35	2000-2005	Not compatible with Premium Amplified Systems. For 12+6 pin radio connectors.	PPH7550	YES
	J30	1995-1997	Not compatible with Premium Amplified Systems. For 12+6 pin radio connectors.	PPH7550	YES
	Q45	1994-2001	Not compatible with Premium Amplified Systems. For 12+6 pin radio connectors.	PPH7550	YES
	QX4	1997-2005	Not compatible with Premium Amplified Systems. For 12+6 pin radio connectors.	PPH7550	YES
Isuzu	Amigo	1998-2000	For 16 pin radio connectors.	PPH7712	YES
	Hombre	1996-2000	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Oasis	1996-1999	For 16 pin radio connectors.	PPH1720	YES
	Rodeo	1996-2005	For 16 pin radio connectors.	PPH7712	YES
	Trooper	1996-2002	For 16 pin radio connectors.	PPH7712	YES
	Vehicross	1999-2001	For 16 pin radio connectors.	PPH7712	YES
Jeep	Cherokee	1997-2001	For 17 pin radio connectors.	PPH1817	YES
	Grand Cherokee	2002-2006	For 22 pin radio connectors. Not compatible with Infinity premium amplifiers.	PPH1818	YES
	Grand Cherokee	1992-2001	For 17 pin radio connectors.	PPH1817	YES
	Liberty	2002-2006	For 22 pin radio connectors.	PPH1818	YES
	Vision	1993-1997	For 17 pin radio connectors.	PPH1817	YES
	Wrangler	2003-2006	For 22 pin radio connectors.	PPH1818	YES
	Wrangler	1997-2002	For 17 pin radio connectors.	PPH1817	YES
Lexus	LX450	1996-1997	Not compatible with Premium Amplified or other external amplifiers.. For 10+6 pin radio connectors.	PPH1761	YES
Lincoln	Aviator	2003-2005	Make sure radio has No phone symbol on radio buttons.. Not compatible with premium amplified systems.. For 16 pin radio connectors.	PPH1771	YES
	Aviator	2003-2005	Not compatible with Premium Amplified Systems. For 24 pin radio connectors.	PPH5800	YES
	Aviator	2003-2005	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio.	PXFDHF	NO
	Aviator	2003-2005	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS1	NO
	Aviator	2003-2005	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors.	PXFDHF2	NO
	Aviator	2003-2005	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS2	NO
	Blackwood	2002-2003	Make sure radio has No phone symbol on radio buttons.. Not compatible with premium amplified systems.. For 16 pin radio connectors.	PPH1771	YES
	Blackwood	2002-2003	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio.	PXFDHF	NO
	Blackwood	2002-2003	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS1	NO
	Continental	1998-2005	Make sure radio has No phone symbol on radio buttons.. Not compatible with premium amplified systems.. For 16 pin radio connectors.	PPH1771	YES
	Continental	1998-2005	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio.	PXFDHF	NO
	Continental	1998-2005	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS1	NO
	Continental	1984-1994	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
	LS	2004-2005	Not compatible with Premium Amplified Systems. For 24 pin radio connectors.	PPH5800	YES
	LS	2004-2005	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors.	PXFDHF2	NO
	LS	2004-2005	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS2	NO
	LS	2000-2003	Make sure radio has No phone symbol on radio buttons.. Not compatible with premium amplified systems.. For 16 pin radio connectors.	PPH1771	YES
	LS	2000-2003	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio.	PXFDHF	NO
	LS	2000-2003	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS1	NO
	Mark LT	2006-2007	Not compatible with Premium Amplified Systems. For 24 pin radio connectors.	PPH5800	YES
	Mark LT	2006-2007	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors.	PXFDHF2	NO
	Mark LT	2006-2007	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS2	NO
	Mark VII	1986-1993	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
	Mark VIII	1993-1994	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
	MKX	2007-2008	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS2	NO
	Navigator	2003-2006	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors.	PXFDHF2	NO
	Navigator	2003-2006	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS2	NO
	Navigator	1998-2004	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio.	PXFDHF	NO
Navigator	1998-2004	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS1	NO	
Navigator	1998-2004	Make sure radio has No phone symbol on radio buttons.. Not compatible with premium amplified nor Navigation systems. For 16 pin radio connectors.	PPH1771	YES	

	Town Car	2003-2007	Not compatible with Premium Amplified Systems. For 24 pin radio connectors.	PPH5800	YES
	Town Car	2003-2007	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors.	PXFDHF2	NO
	Town Car	2003-2007	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS2	NO
	Town Car	1998-2002	Make sure radio has No phone symbol on radio buttons.. Not compatible with premium amplified systems.. For 16 pin radio connectors.	PPH1771	YES
	Town Car	1998-2002	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio.	PXFDHF	NO
	Town Car	1998-2002	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS1	NO
	Town Car	1987-1994	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
	Zephyr	2006	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors.	PXFDHF2	NO
	Zephyr	2006	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS2	NO
Mazda	B Series Pickup	1998-2001	Make sure radio has No phone symbol on radio buttons.. Not compatible with premium amplified systems.. For 16 pin radio connectors.	PPH1771	YES
	B Series Pickup	1994-1997	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
	Navajo	1991-1994	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
	Truck	2002-2005	Make sure radio has No phone symbol on radio buttons.. Not compatible with premium amplified systems.. For 16 pin radio connectors.	PPH1771	YES
Mercedes	C-Class	2002-2004	For 16 pin radio connectors.	PPH1784	YES
Mercury	Capri	1991-1994	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
	Capri	1986	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
	Cougar	2001-2002	Make sure radio has No phone symbol on radio buttons.. Not compatible with premium amplified systems.. For 16 pin radio connectors.	PPH1771	YES
	Cougar	2001-2002	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio.	PXFDHF	NO
	Cougar	2001-2002	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS1	NO
	Cougar	1999-2000	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
	Cougar	1986-1997	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
	Grand Marquis	2003-2005	Not compatible with Premium Amplified Systems. For 24 pin radio connectors.	PPH5800	YES
	Grand Marquis	2003-2005	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors.	PXFDHF2	NO
	Grand Marquis	2003-2005	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS2	NO
	Grand Marquis	1998-2002	Make sure radio has No phone symbol on radio buttons.. Not compatible with premium amplified systems.. For 16 pin radio connectors.	PPH1771	YES
	Grand Marquis	1998-2002	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio.	PXFDHF	NO
	Grand Marquis	1998-2002	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS1	NO
	Grand Marquis	1985-1994	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
	Lynx	1986-1987	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
	Marauder	2003-2005	Not compatible with Premium Amplified Systems. For 24 pin radio connectors.	PPH5800	YES
	Marauder	2003-2005	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors.	PXFDHF2	NO
	Marauder	2003-2005	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS2	NO
	Mariner	2005-2007	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors.	PXFDHF2	NO
	Mariner	2005-2007	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS2	NO
	Mariner Hybrid	2006-2007	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors.	PXFDHF2	NO
	Mariner Hybrid	2006-2007	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS2	NO
	Mark LT	2006	Not compatible with Premium Amplified Systems. For 24 pin radio connectors.	PPH5800	YES
	Milan	2006-2007	Not compatible with Premium Amplified Systems. For 24 pin radio connectors.	PPH5800	YES
	Milan	2006-2007	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors.	PXFDHF2	NO
	Milan	2006-2007	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS2	NO
	Montego	2005-2007	Not compatible with Premium Amplified Systems. For 24 pin radio connectors.	PPH5800	YES
	Montego	2005-2007	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors.	PXFDHF2	NO
	Montego	2005-2007	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS2	NO
	Monterey	2004-2007	Not compatible with Premium Amplified Systems. For 24 pin radio connectors.	PPH5800	YES
	Monterey	2004-2007	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors.	PXFDHF2	NO
	Monterey	2004-2007	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS2	NO
	Mountaineer	2004-2005	Not compatible with Premium Amplified Systems. For 24 pin radio connectors.	PPH5800	YES
	Mountaineer	2004-2005	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors.	PXFDHF2	NO

	Mountaineer	2004-2005	Must have a phone symbol on the radio and the radio must be turned on to operate. For 24+16 pin radio connectors. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS2	NO
	Mountaineer	1998-2003	Make sure radio has No phone symbol on radio buttons.. Not compatible with premium amplified systems.. For 16 pin radio connectors.	PPH1771	YES
	Mountaineer	1998-2003	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio.	PXFDHF	NO
	Mountaineer	1998-2003	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS1	NO
	Mountaineer	1995-1997	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
	Mystique	1995-2000	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
	Sable	1986-1995	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
	Topaz	1986-1994	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
	Tracer	1991-1996	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
	Villager	1999-2002	Make sure radio has No phone symbol on radio buttons.. Not compatible with premium amplified systems.. For 16 pin radio connectors.	PPH1771	YES
	Villager	1999-2002	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio.	PXFDHF	NO
	Villager	1999-2002	Radio must have a Phone button on the face of the radio. For 20 pin radio connectors. Not compatible with Navigation radio. Requires MOT1000 harness when using with IHF1000 (sold separately)	FCSS1	NO
	Villager	1993-1998	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
Mini					
	Cooper	2002-2005	For 16 pin radio connectors.	PPH9003	YES
Mitsubishi					
	3000GT	1994-1999	For 14 pin radio connectors.	PPH7001	YES
	Diamante	1994-2003	For 14 pin radio connectors.	PPH7001	YES
	Eclipse	1995-2005	For 14 pin radio connectors.	PPH7001	YES
	Gallant	1994-2003	For 14 pin radio connectors.	PPH7001	YES
	Lancer	2002-2006	For 14 pin radio connectors.	PPH7001	YES
	Mirage	1997-2002	For 14 pin radio connectors.	PPH7001	YES
	Montero / Sport	1997-2006	For 14 pin radio connectors.	PPH7001	YES
	Outlander	2003-2006	For 14 pin radio connectors.	PPH7001	YES
Nissan					
	100 NX	1991-2005	Not compatible with Rockford Fosgate or Subwoofers (9+ speaker systems). For 12+6 pin radio connectors.	PPH7550	YES
	200 SX	1989-2005	Not compatible with Rockford Fosgate or Subwoofers (9+ speaker systems). For 12+6 pin radio connectors.	PPH7550	YES
	200SX	1995-1998	For 12+6 pin radio connectors.	PPH7550	YES
	240SX	1995-1998	For 12+6 pin radio connectors.	PPH7550	YES
	300 ZX	1997-2005	Not compatible with Rockford Fosgate or Subwoofers (9+ speaker systems). For 12+6 pin radio connectors.	PPH7550	YES
	350Z	2003-2005	Not compatible with Rockford Fosgate or Subwoofers (9+ speaker systems). For 12+6 pin radio connectors.	PPH7550	YES
	Almera	1995-2000	For 12+6 pin radio connectors.	PPH7550	YES
	Altima	2004-2006	Not compatible with Rockford Fosgate or Subwoofers (9+ speaker systems). For 12+6 pin radio connectors.	PPH7550	YES
	Altima	1995-2005	For 12+6 pin radio connectors.	PPH7550	YES
	Bluebird	1986-1990	For 12+6 pin radio connectors.	PPH7550	YES
	Cabstar	2000-2005	Not compatible with Rockford Fosgate or Subwoofers (9+ speaker systems). For 12+6 pin radio connectors.	PPH7550	YES
	Cargo	1993-2005	Not compatible with Rockford Fosgate or Subwoofers (9+ speaker systems). For 12+6 pin radio connectors.	PPH7550	YES
	Frontier	1998-2006	Not compatible with Rockford Fosgate or Subwoofers (9+ speaker systems). For 12+6 pin radio connectors.	PPH7550	YES
	Frontier Pickup	2005	Not compatible with Rockford Fosgate or Subwoofers (9+ speaker systems). For 12+6 pin radio connectors.	PPH7550	YES
	Hardbody Pickup	1995-1997	For 12+6 pin radio connectors.	PPH7550	YES
	King Cab	1986-2005	Not compatible with Rockford Fosgate or Subwoofers (9+ speaker systems). For 12+6 pin radio connectors.	PPH7550	YES
	King Van	1990-2005	Not compatible with Rockford Fosgate or Subwoofers (9+ speaker systems). For 12+6 pin radio connectors.	PPH7550	YES
	Maxima	1995-2006	Not compatible with Rockford Fosgate or Subwoofers (9+ speaker systems). For 12+6 pin radio connectors.	PPH7550	YES
	Micra	1988-2005	Not compatible with Rockford Fosgate or Subwoofers (9+ speaker systems). For 12+6 pin radio connectors.	PPH7550	YES
	Murano	2003-2007	Not compatible with Rockford Fosgate or Subwoofers (9+ speaker systems). For 12+6 pin radio connectors.	PPH7550	YES
	Navara	2000-2005	Not compatible with Rockford Fosgate or Subwoofers (9+ speaker systems). For 12+6 pin radio connectors.	PPH7550	YES
	Pathfinder	2005-2006	Not compatible with Rockford Fosgate or Subwoofers (9+ speaker systems). For 12+6 pin radio connectors.	PPH7550	YES
	Pathfinder	1995-2006	Not compatible with Rockford Fosgate or Subwoofers (9+ speaker systems). For 12+6 pin radio connectors.	PPH7550	YES
	Pathfinder	2005	Not compatible with Rockford Fosgate or Subwoofers (9+ speaker systems). For 12+6 pin radio connectors.	PPH7550	YES
	Patrol	1989-2005	Not compatible with Rockford Fosgate or Subwoofers (9+ speaker systems). For 12+6 pin radio connectors.	PPH7550	YES
	Praire	1991-1995	For 12+6 pin radio connectors.	PPH7550	YES
	Primera P11E	1996-1999	For 12+6 pin radio connectors.	PPH7550	YES
	Pulsar	1996-2005	Not compatible with Rockford Fosgate or Subwoofers (9+ speaker systems). For 12+6 pin radio connectors.	PPH7550	YES

	Quest	004-2006+C57	Not compatible with Rockford Fosgate or Subwoofers (9+ speaker systems). For 12+6 pin radio connectors.	PPH7550	YES
	Quest	1999-2003	Make sure radio has No phone symbol on radio buttons.. Not compatible with premium amplified systems.. For 16 pin radio connectors.	PPH1771	YES
	Quest	1993-1998	Not compatible with premium amplified systems . For 8+8 pin radio connectors.	PPH1770	YES
	Sentra	1995-2007	Not compatible with Rockford Fosgate or Subwoofers (9+ speaker systems). For 12+6 pin radio connectors.	PPH7550	YES
	Serena	1993-2000	For 12+6 pin radio connectors.	PPH7550	YES
	Sunny	1987-2005	Not compatible with Rockford Fosgate or Subwoofers (9+ speaker systems). For 12+6 pin radio connectors.	PPH7550	YES
	Terrano	1987-1997	For 12+6 pin radio connectors.	PPH7550	YES
	Terrano II	2000-2005	Not compatible with Rockford Fosgate or Subwoofers (9+ speaker systems). For 12+6 pin radio connectors.	PPH7550	YES
	Titan	2004-2007	Not compatible with Rockford Fosgate or Subwoofers (9+ speaker systems). For 12+6 pin radio connectors.	PPH7550	YES
	Vanette	1993-2000	For 12+6 pin radio connectors.	PPH7550	YES
	Xterra	000-2006+C59	Not compatible with Rockford Fosgate or Subwoofers (9+ speaker systems). For 12+6 pin radio connectors.	PPH7550	YES
Oldsmobile					
	Achieva	1996-1998	Not compatible with Decks with external amplifiers.. For 32 pin radio connectors.	PPH2001	YES
	Achieva	1992-1995	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Alero	2001-2004	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS2	NO
	Alero	1999-2000	Not compatible with Decks with external amplifiers.. For 32 pin radio connectors.	PPH2001	YES
	Aurora	1995-2000	Not compatible with Decks with external amplifiers.. For 32 pin radio connectors.	PPH2001	YES
	Bravada	2002-2005	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS2	NO
	Bravada	1998-2001	Not compatible with Decks with external amplifiers.. For 32 pin radio connectors.	PPH2001	YES
	Bravada	1991-1997	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Cutlass Calais	1990-1991	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Cutlass Ciera	1988-1996	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Cutlass Supreme	1995-1997	Not compatible with Decks with external amplifiers.. For 32 pin radio connectors.	PPH2001	YES
	Cutlass Supreme	1990-1994	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Eighty Eight	1994-1999	Not compatible with Decks with external amplifiers.. For 32 pin radio connectors.	PPH2001	YES
	Eighty Eight	1989-1993	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Intrigue	1998-2002	Not compatible with Decks with external amplifiers.. For 32 pin radio connectors.	PPH2001	YES
	LSS	1996-1999	Not compatible with Decks with external amplifiers.. For 32 pin radio connectors.	PPH2001	YES
	Ninety Eight	1994-1996	Not compatible with Decks with external amplifiers.. For 32 pin radio connectors.	PPH2001	YES
	Ninety Eight	1989-1993	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Regency	1994-1998	Not compatible with Decks with external amplifiers.. For 32 pin radio connectors.	PPH2001	YES
	Silhouette	2000-2005	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS2	NO
	Silhouette	1990-1999	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Toronado	1990-1992	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
Plymouth					
	Acclaim	1989-1995	For 17 pin radio connectors.	PPH1817	YES
	Breeze	1996-2000	For 17 pin radio connectors.	PPH1817	YES
	Gran Fury	1984-1989	For 17 pin radio connectors.	PPH1817	YES
	Horizon	1984-1990	For 17 pin radio connectors.	PPH1817	YES
	Neon	1995-2001	For 17 pin radio connectors.	PPH1817	YES
	Prowler	1997-2001	For 17 pin radio connectors.	PPH1817	YES
	Reliant	1981-1989	For 17 pin radio connectors.	PPH1817	YES
	Sundance	1987-1994	For 17 pin radio connectors.	PPH1817	YES
	Voyager	1984-2001	For 17 pin radio connectors.	PPH1817	YES
Pontiac					
	6000	1990-1991	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Aztec	2001-2005	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS2	NO
	Bonneville	1992-1999	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Firebird	1990-2002	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Grand Am	2001-2005	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS2	NO
	Grand Am	1990-2000	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Grand Prix	2004-2007	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS2	NO
	Grand Prix	1988-2003	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	GTO	2004-2005	For 16 pin radio connectors.	PPH1784	YES
	Montana	2000-2006	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS2	NO
	Montana	1999	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Sunbird	1989-1994	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Sunfire	2000-2005	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS2	NO
	Sunfire	1995-1999	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Trans Am	1990-2002	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES

	Trans Sport	1990-1999	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	Vibe	2003-2006	Not compatible with RDS radio or amplified systems.. For 24 pin radio connectors.	PPH2003	YES
	Vibe	2006-2007	Vehicle must have OnStar and a have phone symbol on the face of the radio. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS2	NO
Porsche					
	911	1977-2005	For 16 pin radio connectors.	PPH1784	YES
	928	1978-1995	For 16 pin radio connectors.	PPH1784	YES
	944	1982-1990	For 16 pin radio connectors.	PPH1784	YES
	968	1991-2005	For 16 pin radio connectors.	PPH1784	YES
	996	1998-2005	For 16 pin radio connectors.	PPH1784	YES
	924 924S	1976-1988	For 16 pin radio connectors.	PPH1784	YES
	Cayenne	2003-2004	For 16 pin radio connectors.	PPH1784	YES
Saturn					
	Outlook	2007	Vehicle must have OnStar Installed. Requires MOT1000 Harness when using with IHF1000 (sold separately)	GMCSS3	NO
	SC	1991-1999	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	SL	1991-1999	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
	SW	1993-1999	Not compatible with Monsoon or other external amplifiers.. For 21 pin radio connectors.	PPH1858	YES
Scion					
	tC	2005-2006	For 10+6 pin radio connectors.	PPH1761	YES
	xA	2004-2006	For 10+6 pin radio connectors.	PPH1761	YES
	xB	2004-2006	Not compatible with Premium Amplified or other external amplifiers.. For 10+6 pin radio connectors.	PPH1761	YES
Suzuki					
	Aerio	2002-2005	For 20 pin radio connectors.	PPH1721	YES
	Forenza	2004-2005	For 20 pin radio connectors.	PPH1721	YES
	Grand Vitara	2003-2005	For 20 pin radio connectors.	PPH1721	YES
	XL-7	2003-2005	For 20 pin radio connectors.	PPH1721	YES
Toyota					
	4runner	1987-2007	Not compatible with Navigation, JBL, or systems with more than 6 speakers.. For 10+6 pin radio connectors.	PPH1761	YES
	Avalon	1995-1999	Not compatible with Navigation, JBL, or systems with more than 6 speakers.. For 10+6 pin radio connectors.	PPH1761	YES
	Camry	1987-2007	Not compatible with Navigation, JBL, or systems with more than 6 speakers.. For 10+6 pin radio connectors.	PPH1761	YES
	Camry Solara	1999-2006	Not compatible with Navigation, JBL, or systems with more than 6 speakers.. For 10+6 pin radio connectors.	PPH1761	YES
	Camry Solara Coupe	2006	Not compatible with Navigation, JBL, or systems with more than 6 speakers.. For 10+6 pin radio connectors.	PPH1761	YES
	Celica	1989-2005	Not compatible with Navigation, JBL, or systems with more than 6 speakers.. For 10+6 pin radio connectors.	PPH1761	YES
	Corolla	1987-2007	Not compatible with Navigation, JBL, or systems with more than 6 speakers.. For 10+6 pin radio connectors.	PPH1761	YES
	Cressida	1987-1992	Not compatible with Navigation, JBL, or systems with more than 6 speakers.. For 10+6 pin radio connectors.	PPH1761	YES
	Echo	2000-2005	Not compatible with Navigation, JBL, or systems with more than 6 speakers.. For 10+6 pin radio connectors.	PPH1761	YES
	Highlander	2001-2007	Make sure radio has 6 Speaker systems. Not compatible with Navigation, JBL, or systems with more than 6 speakers.. For 10+6 pin radio connectors.	PPH1761	YES
	Landcruiser	1987-2002	Not compatible with Navigation, JBL, or systems with more than 6 speakers.. For 10+6 pin radio connectors.	PPH1761	YES
	Matrix	2005-2007	Not compatible with Navigation, JBL, or systems with more than 6 speakers.. For 10+6 pin radio connectors.	PPH1761	YES
	Matrix	2003-2004	Not compatible with RDS radio or amplified systems.. For 24 pin radio connectors.	PPH2003	YES
	MR2	1987-1995	Not compatible with Navigation, JBL, or systems with more than 6 speakers.. For 10+6 pin radio connectors.	PPH1761	YES
	MR2 Spider	2000-2006	Not compatible with Navigation, JBL, or systems with more than 6 speakers.. For 10+6 pin radio connectors.	PPH1761	YES
	Paseo	1992-1995	Not compatible with Navigation, JBL, or systems with more than 6 speakers.. For 10+6 pin radio connectors.	PPH1761	YES
	Pickup	1987-1995	Not compatible with Navigation, JBL, or systems with more than 6 speakers.. For 10+6 pin radio connectors.	PPH1761	YES
	Previa	1991-1997	Not compatible with Navigation, JBL, or systems with more than 6 speakers.. For 10+6 pin radio connectors.	PPH1761	YES
	Prius	2001-2003	Not compatible with Navigation, JBL, or systems with more than 6 speakers.. For 10+6 pin radio connectors.	PPH1761	YES
	RAV4	1996-2007	Not compatible with Navigation, JBL, or systems with more than 6 speakers.. For 10+6 pin radio connectors.	PPH1761	YES
	Sequoia	2001-2005	Not compatible with Navigation, JBL, or systems with more than 6 speakers.. For 10+6 pin radio connectors.	PPH1761	YES
	Sienna	1998-2003	Not compatible with Navigation, JBL, or systems with more than 6 speakers.. For 10+6 pin radio connectors.	PPH1761	YES
	Solara	1999-2007	Not compatible with Navigation, JBL, or systems with more than 6 speakers.. For 10+6 pin radio connectors.	PPH1761	YES
	Supra	1986-1998	Not compatible with Navigation, JBL, or systems with more than 6 speakers.. For 10+6 pin radio connectors.	PPH1761	YES
	T-100	1993-1998	Not compatible with Navigation, JBL, or systems with more than 6 speakers.. For 10+6 pin radio connectors.	PPH1761	YES
	Tacoma	1995-2007	Not compatible with Navigation, JBL, or systems with more than 6 speakers.. For 10+6 pin radio connectors.	PPH1761	YES
	Tercel	1987-1998	Not compatible with Navigation, JBL, or systems with more than 6 speakers.. For 10+6 pin radio connectors.	PPH1761	YES

	Tundra	2000-2007	Not compatible with Navigation, JBL, or systems with more than 6 speakers.. For 10+6 pin radio connectors.	PPH1761	YES
	Van	1987-1990	Not compatible with Navigation, JBL, or systems with more than 6 speakers.. For 10+6 pin radio connectors.	PPH1761	YES
	Yaris	2007	For 10+6 pin radio connectors.	PPH1761	YES
Volkswagen					
	Beetle	2002-2006	Not compatible with OnStar. For 16 pin radio connectors.	PXVWHF1	NO
	Beetle	1998-2006	Make sure radio has OnStar. Not compatible with Monsoon Premium Amplified sound system.. For 16 pin radio connectors.	PPH1784	YES
	Bora	1998-2005	For 16 pin radio connectors.	PPH1784	YES
	Cabrio	2002-2006	For 16 pin radio connectors.	PPH9003	YES
	Cabrio	2002-2006	Not compatible with Onstar. For 12 pin radio connectors.	PXVWHF2	NO
	Cabrio	1995-2001	Not compatible with Monsoon nor Double DIN, nor Premium 6. For 16 pin radio connectors.	PPH1784	YES
	Cabriolet	1987-1994	Not compatible with Monsoon nor Double DIN, nor Premium 6. For 16 pin radio connectors.	PPH1784	YES
	Caddy (pick-up)	1995-2005	Not compatible with Monsoon nor Double DIN, nor Premium 6. For 16 pin radio connectors.	PPH1784	YES
	Caravelle	1991-2005	Not compatible with Monsoon nor Double DIN, nor Premium 6. For 16 pin radio connectors.	PPH1784	YES
	Corrado	1989-1995	Not compatible with Monsoon, Double DIN, or Premium 6. For 16 pin radio connectors.	PPH1784	YES
	Eurovan	1999-2005	Not compatible with Monsoon, Double DIN, or Premium 6. For 16 pin radio connectors.	PPH1784	YES
	Fox	1987-1994	Not compatible with Monsoon, Double DIN, or Premium 6. For 16 pin radio connectors.	PPH1784	YES
	Golf // GTI	2002-2008	For 16 pin radio connectors.	PPH9003	YES
	Golf / GTI	2002-2006	Not compatible with Onstar. For 12 pin radio connectors.	PXVWHF2	NO
	Golf / GTI	1980-2001	Not compatible with Monsoon, Double DIN, or Premium 6. For 16 pin radio connectors.	PPH1784	YES
	Jetta	2002-2008	For 16 pin radio connectors.	PPH9003	YES
	Jetta	2002-2006	Not compatible with Onstar. For 12 pin radio connectors.	PXVWHF2	NO
	Jetta	1985-2001	Not compatible with Monsoon, Double DIN, or Premium 6. For 16 pin radio connectors.	PPH1784	YES
	Multivan	2003-2005	Not compatible with Monsoon, Double DIN, or Premium 6. For 16 pin radio connectors.	PPH1784	YES
	Passat	2002-2008	For 16 pin radio connectors.	PPH9003	YES
	Passat	2001-2006	Not compatible with Onstar. For 12 pin radio connectors.	PXVWHF2	NO
	Passat	1990-2000	Not compatible with Monsoon, Double DIN, or Premium 6. For 16 pin radio connectors.	PPH1784	YES
	Quantum	1986-1988	Not compatible with Monsoon, Double DIN, or Premium 6. For 16 pin radio connectors.	PPH1784	YES
	R32	2004-2006	Not compatible with Monsoon, Double DIN, or Premium 6. For 16 pin radio connectors.	PPH1784	YES
	R32	2004-2006	Not compatible with OnStar. For 12 pin radio connectors.	PXVWHF2	NO
	Scirocco	1987-1988	Not compatible with Monsoon, Double DIN, or Premium 6. For 16 pin radio connectors.	PPH1784	YES
	Sharan	1995-2005	Not compatible with Monsoon, Double DIN, or Premium 6. For 16 pin radio connectors.	PPH1784	YES
	Touareg	2003-2007	For 16 pin radio connectors.	PPH9003	YES
	Touareg	2003-2006	Make sure radio has Standard tuner. Non-OnStar. Not compatible with Onstar. For 12 pin radio connectors.	PXVWHF2	NO
	Transporter & T4	1996-2003	Not compatible with Monsoon, Double DIN, or Premium 6. For 16 pin radio connectors.	PPH1784	YES
	Vanagon	1986-1992	Not compatible with Monsoon, Double DIN, or Premium 6. For 16 pin radio connectors.	PPH1784	YES